







MEYLE[®]
Products

| | MEYLE No. | Reference No. |
|---------------------|-----------------|---------------|
| Control arm bushing | 014 033 0000/HD | 202 333 64 14 |
| Repair kit | 014 033 0016/HD | 202 330 00 75 |
| Control arm | 016 050 0004/HD | 170 330 01 07 |
| | 016 050 0005/HD | 170 330 02 07 |

Control arm bushing, front axle to fit Mercedes R 170, S/W 202



|   Problem |   Solution |
|--|---|
| <p>Excessive strain of the rubber to metal compound due to increased dynamic forces</p> | <ul style="list-style-type: none"> • Strengthening and optimizing the rubber to metal compound consistency • Use of higher quality elastomer |
| <p>Effect</p> | <p>Advantage</p> |
| <p>Loud noise and reduction of the driving safety</p> | <p>Significant longer lifetime</p> |

MEYLE - Miles in Motion

© MEYLE Products® - Wulf Gaertner Autoparts AG • Log.2006
Merkurring 111 • 22143 Hamburg • Germany
contact@meyle.com • www.meyle.com